




OWNER: Brendan Cunningham. 4 Cherry Tree Close, NN14 2SF

# Extra Service/Repair/Upgrade :

Date	Miles	Notes	
24/04/2015	39330	Remove all 4 wheels, check tyres and brakes. Regrease wheel mounting and fit new wheel centre caps.	
31/07/2015	39504	Front anti-roll bar drop-links. Rubber dry, split and perished. New bushes and new AM cup washers fitted. All related parts waxoyled.	
04/08/2015	39556	<p>Slight knock from RH front end. Removed shock absorbers and checked operation and bushes. Function of SA fine, and all bushes in good condition apart from rusted cup washers at top. Fitted new top mounting kits as known weakness. Body mounting plate front top mounts showing early signs of surface rust as expected so cleaned and Waxoyled. All components inspected, surface rust removed and thoroughly Waxoyled. New high tensile bolts and nuts for bottom mount.</p>	
24/05/2016 To	40524	<p>Taken to Paint FX in Kettering for full respray. This was decided upon due to several small but annoying blemishes and a poor finish on the nose cone following a pre-purchase stone chip removal respray. There was also slight bubbling around the front and rear screens. The owner of Paint FX, Tim, was happy for me to work alongside his team. The car was fully stripped including removal of front and rear sections, side skirts, lights, handles, both front and rear screens. Once stripped down, the state of the bodywork could be assessed. Having been warned about rust on these cars I was very pleased to find that there was no evidence of rust at all other than minor surface blemishes on some edges.</p>	



OWNER: Brendan Cunningham. 4 Cherry Tree Close, NN14 2SF



*(Sill shots showing zero rust – pre Waxoyl).*

The bubbling in two places around the screens turned out to be caused by previous glass replacement and not more serious rot. The bubbling was purely a surface blemish (Note – I was present for glass refit and great care was taken to ensure no repeat).


The tray below the valance in front of the windscreen was totally rust free. The respray involved extra thick lacquer and subsequent flatting and polishing to achieve the desired finish.

When reassembling the car it was decided for longevity to use copious amounts of Waxoyl on “under” surfaces rather than aim for a concours paint finish.





OWNER: Brendan Cunningham. 4 Cherry Tree Close, NN14 2SF

		Note: See signed declaration from Tim Pugh (owner Paint FX) that the respray was for upgrade/improvement and not due to any damage repair.
24/05/2016	40524	<p>Front bonnet vent install – alongside respray.            Jaguar bonnet vents were installed to improve heat dissipation and as an aesthetic choice. The vents were enhanced and strengthened using aluminium mesh.            A mirror image card template was made to ensure accurate and symmetrical vent placement.</p>
24/05/2016	40524	<p>Rear boot lip spoiler – alongside respray.            The upswept tail of the DB7 GT/GTA appealed, but cost and my desire for individuality lead me to design and make a removable lip spoiler. I made this from a Mercedes CLK unit, which had to be cut, bent, reset and reshaped to fit the DB7.</p>  <p><i>(Shows jig to reshape and twist pre-cut spoiler. New GRP core to hold shape).</i>            The spoiler is attached using high quality tape and so can be removed if desired.</p>
24/05/2016	40524	<p>The dipped main beam lights were converted to HID.            All other exterior lights were replaced with LED lamps.</p>
24/05/2016	40124	Rear subwoofer upgrade begun with aperture cut into rear deck and grille fitted.
15/06/2016	40124	Receiver drier renew (as easy access due to nose cone removal) and full A/C service by Bee Cool.
08/07/2016	40124	Traffic camera install. See additional wiring diagram Add 5.0
16/07/2016	40124	Resistor and heat sink pack to allow correct use of LED in brake lights. See additional wiring diagram Add 1.0 DRL modification with updated wiring.
23/08/2016	40724	<p>Engine misfire. OBD2 scan reveals misfire detected and cylinder 1 coil pack probably defective.            Coil pack issues are well documented for DB7 V12 cars and the mileage was in line with expected failures. A full set of 12 coil packs was ordered from Aston Martin (£960) along with a set of 12 new platinum NGK spark plugs.</p>
02/09/2016	40801	Intermittent poor starting much worse with solenoid relay not engaging. Investigation revealed loose and electrically corroded nut on solenoid contact. New nut attached and all contacts tightened. Access tight.
10/04/2017	41022	Touchtronic Retrofit. BMW E46 shifter mechanism (OEM is also BMW, but much older model, so E46 variant is an update/upgrade). Genuine Touchtronic





OWNER: Brendan Cunningham. 4 Cherry Tree Close, NN14 2SF

steering wheel fitted – simple plug and play. Genuine Touchtronic instrument binnacle fitted. This was assembled from a combination of parts from the original unit and the Touchtronic unit to ensure correct odometer reading is shown. Audi TT selector surround fitted with associated DIY trimming. There were some wiring changes which have been added to my printed workshop manual.



		<p>steering wheel fitted – simple plug and play. Genuine Touchtronic instrument binnacle fitted. This was assembled from a combination of parts from the original unit and the Touchtronic unit to ensure correct odometer reading is shown. Audi TT selector surround fitted with associated DIY trimming. There were some wiring changes which have been added to my printed workshop manual.</p> 